

KYORITSU KT200 CLAMP METER

Measuring Ranges and Accuracy (at 23±5°C, 45-75% relative humidity)

AC Current (A)

Range	Measuring Range	Accuracy
40A	0-39.99A	± 2.0% rdg ± 6dgt (50/60hz)
400A	0-399.9A	

AC Voltage (V) Auto-ranging

Range	Measuring Range	Accuracy
400V	0-399.9V	± 2.0% rdg ± 5dgt (50/60hz)
600V	150-599V	

DC Voltage (V) Auto-ranging

Range	Measuring Range	Accuracy
400V	0-399.9V	± 2.0% rdg ± 5dgt
600V	150-599V	

Resistance (Ω/Continuity) Auto-ranging (Buzzer beeps below 50 ± 35Ω)

Range	Measuring Range	Accuracy
400 Ω	0-399.9 Ω	± 2.0% rdg ± 5dgt
4000 Ω	150-3999 Ω	

